

**ATTENTION!!!**

**NEW SAFETY RECALL 03506**

Special Note: The vins in this recall will show marked in ISIS on 3/14/03.

03V-072

**SUBJECT: ALTERNATOR CABLE TERMINAL MAY BREAK OFF** on  
9100I, 9200I, 9400I, and 9900I models built 6/8/2001  
through 11/4/2002

\* **PRINTING:** To Print an official copy of the dealer letter you must first click on the hotlink found in the next bullet point and then click on the **BLUE PDF HOTLINK** that says "Print ready (PDF file) copy of the dealer letter" (this is only a sample, not the real hotlink). The Print ready files are found under the "DEFECT DESCRIPTION" on the first page of the intranet dealer letter. To print, simply click on the PDF hot link to open the letter and select the print command. The dealer and customer letters will print out as you see them in the PDF file format (which is exactly like the old hard copies).

Please review the campaign letter on our Intranet by clicking on this hotlink [http://service.navistar.com/recalls/03506\\_1.xml](http://service.navistar.com/recalls/03506_1.xml)

\*

\* This message can be forwarded to anyone **INTERNALLY** who needs information on this campaign.

\* Send me an e-mail if you want to add or delete individuals on the distribution list above.

\* **PLEASE MAKE EVERY EFFORT TO GET THESE VEHICLES REPAIRED AS SOON AS POSSIBLE.**

**LOCATION Vehicle Quantities**

US 881

CANADA 29

MEXICO 0

BRAZIL 0

OTHER 0

US DEALER MAILING R: 03/13/03

US CUSTOMER MAILING R: 03/20/03

CANADIAN DEALER MAILING R: 03/13/03

CANADIAN CUSTOMER MAILING R: 03/20/03

\* Please let me know if there are any campaign problems.

\* **THANK YOU**

Mark Clark

Compliance Coordinator

International Truck and Engine Corporation

phone: 260-461-1873

fax: 260-461-1813